

## TEST REPORT

Mechanical & Hardgoods Laboratory

Report No. : TH70144A/2014

Page : 1 of 3

Date: AUG. 12, 2014

**HANLIX INT'L CO., LTD. (Doez International Co., Ltd.)**

No.851, Hexian Rd., Xianxi Township, Changhua County 507, Taiwan (R.O.C.)

**The following merchandise was submitted and identified by the applicant as:**

Product Description: Multi-Purpose Rail

Style/Item No.: 9416601; 9413601; 9410451; 9406301

Country of Origin: TAIWAN

**We have tested the submitted sample(s) as requested and the following results were obtained:**

Test Requested: Static Load Test

- Test Method:
- a. Secure the sample on the testing glass.
  - b. Suspension specific weight evenly on the sample and maintained for 168 hours.
  - c. Visually check and record if the sample dropped or not after testing.
- Note. 1. Test weight requested by the applicant.  
 2. Test environment: Temperature: 20±2 °C; Humidity:60±10%.

Test Result:

Sample	Sample No	Test weight (kg)	Observation
Multi-Purpose Rail	9416601	20	The sample didn't drop after testing.
	9413601	15	The sample didn't drop after testing.
	9410451	10	The sample didn't drop after testing.
	9406301	5	The sample didn't drop after testing.

Date of Receipt: JUL. 16, 2014

Testing Period: JUL. 18, 2014 ~ AUG. 08, 2014

--- See Next Page ---

**Signed for and on behalf of  
SGS Taiwan Ltd.**



Kaini Chen  
Team Leader

Testing Place: No. 9, 14th Rd., Taichung Ind. Park, Taichung City 40755, Taiwan

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

## TEST REPORT

Mechanical & Hardgoods Laboratory

Report No. : TH70144A/2014

Page : 2 of 3

– Picture(s) –



Photo “A” Appearance of sample: 9416601



Photo “B” Appearance of sample: 9413601




Photo “C” Appearance of sample: 9410451



Photo “D” Appearance of sample: 9406301

--- See Next Page ---

## TEST REPORT

Mechanical & Hardgoods Laboratory

Report No. : TH70144A/2014

Page : 3 of 3

– Picture(s) –



Photo "E" Static Load Test: 9416601



Photo "F" Static Load Test: 9413601



Photo "G" Static Load Test: 9410451




Photo "H" Static Load Test: 9406301

--- End of Report ---